HTIRC03-014

ABSTRACT

The traditional single pole perpendicular writer has two major problems --insufficient field gradient in the down track direction and adjacent track erasure (ATE)
caused by side fringing fields. These problems have been overcome by tapering the main
pole and then shielding it on all four sides.